

NTSB National Transportation Safety Board

Office of Aviation Safety

Opening Remarks





Joseph Sedor Investigator-in-Charge

Accident Summary

- Comair flight 5191
- Bombardier CL-600, N431CA
- August 27, 2006
- 49 fatalities, 1 serious injury
- Airplane destroyed
- NTSB full Go-Team
 - Member Hersman (member on scene)
 - Vice Chairman Sumwalt









Accident Summary

- 6 a.m. departure
- Last of three airplanes
- No rain
- Dark







Findings

- No pre-existing airplane failures
- No restrictions to visibility
- Flight crew
 - Properly certificated
 - No medical factors
- Timely emergency response



Major Areas of Investigation

- Flight crew operations
- Air traffic control
- Human performance
 - Flight crew
 - Air traffic control
- Airport environment



Safety Recommendations

Issued

- 6 safety recommendations
 - -2 flight crew procedures (Dec. 2006)
 - 4 air traffic control (April 2007)

Proposed

- 5 safety recommendations
- 2 reiterated safety recommendations



Comair 5191 NTSB Staff

Bill Bramble

John Brannen

Tim Burtch

Evan Byrne

Pocholo Cruz

Jason Fedok

Pete Hall

Tom Jacky

Sarah McComb

Brian Murphy

Harry Reichel

Al Reitan

Greg Salottolo

Karen Stein

Terry Williams

Dave Tew



Comair 5191 NTSB Staff

Reshan Beal

Eunice Bellinger

Sally Bennett

Bob Benzon

Sharon Bryson

Noel Coleman

Antion Downs

Erik Grosof

Vince Harris

Ed Malinowski

Jeff Marcus

Sandy Rowlett

Paul Sledzik

Christy Spangler

Ken Suydam



ICAO Annex 13

Accredited Representative

Transportation Safety Board of Canada

Advisors

- Bombardier
- Transport Canada



Parties to the Investigation

- Air Line Pilots Association
- Blue Grass Airport
- Comair, Inc.
- Federal Aviation Administration
- GE Transportation, Aircraft Engines
- International Association of Machinists and Aerospace Workers
- National Air Traffic Controllers Association
- Teamsters Local 513 (Flight Attendants)





NTSB